FORM - E

FORM OF REPORT TO BE MADE TO THE COMPETENT AUTHORITY BY INSPECTING AUTHORITES OR OFFICERS APPOINTED UNDER OTHER ACTS UNDER SECTION 28 OF THE TAMIL NADU PUBLIC BUILDINGS (LICENSING) ACT, 1965 (TAMIL NADU ACT XIII OF 1965) REFERRED TO IN RULE 7 OF THE TAMIL NADU PUBLIC BUILDINGS (LICENSING) RULES, 1966.

Name and designation of inspecting
Authority or officer appointed or Having
Jurisdiction Under any other Act or law

Er.G.RUTHRA PRABHU.
B.E.,M.I.E.,F.I.V.,M.E(Struct).,
24-A Kasim Sahib Street,
C.Pallavaram,Chennai-600043.

2. Location of the building inspected

"SAIRAM LEOMUTHU PUBLIC SCHOOL" (Managed by LEOMUTHU Educational Trust, Chennai-17).

Mambakkam – Medavakkam Main Road, Vengaivasal, Chennai-600100. Comprised in Old S.Nos.8/2A1, 8/2A2 (Document), New S.Nos.8/2A1A1, 8/2A1A2, 8/2A2A1 & 8/2A2A2 of Vengaivasal Village, Tambaram Taluk, Chengalpattu District.

Municipalty / Panchayat / Panchayat Union / Township / Contonment

Saint Thomas Mount Panchayat Union Limits., @ Chitlapakkam.

4. Date of inspection

27.10.2023

Purpose for which the building is used

Power Room for the School.

6. Nature of defects noticed

Nil (Maintained Properly)

7. Suggestion for rectifying defects

Does Not arise

If in a dangerous condition
 Immediate action Recommended be taken
 For SAIRAM LEO MUTHU PUBLIC SCHOOL

No (good condition)

Date: 30.10.2023

+



Signature of Inspecting Authority / Officer
Appointed or having jurisdiction
G. RUTHRA PRABHU, B.L., M.L., M.L., C. L., L.Y.,
Consulting Civil, Structural & Charlered Engineer,
Panel of Private Practicing Engineer, Class I-A,
Govt. of the Tamilnadu

Approved by District Collector, Chengalpattu, Rc. No : 4758 / 2020 / M1 Dated : 29.6.2021 Mobile : 98410 21097 / 90808 72965